



Version: V2.10.05
Published: 2010/08/23

The release notes include important information about revisions of D-Link SmartConsole Utility. Please check the new functions and see whether any problem is solved.

For more detailed information regarding D-Link switch products, please refer to [Related Documentation](#).

You can also download the switch firmware, D-View modules and technical documentation from <http://tsd.dlink.com.tw>.

Supporting Model List:

| Product Line | Model Name |
|--------------|-----------------|
| Smart II | DES-1228 |
| | DES-1228P |
| | DES-1252 |
| | DGS-1216T |
| | DGS-1224T |
| | DGS-1224TP |
| | DGS-1248T |
| Smart III | DES-1210 series |
| | DGS-1210 series |

Revision History:

| Version | Release Date |
|----------|--------------|
| v2.10.05 | 2010/08/23 |
| v2.10.02 | 2009/07/07 |
| v2.01.09 | 2009/02/11 |
| v2.01.06 | 2008/04/26 |
| v1.07 | 2007/03/26 |
| v1.06 | 2006/09/28 |
| v1.05 | 2006/04/01 |
| v1.04 | 2006/3/15 |

New Features:

| Version | New Features |
|----------|---|
| v2.10.05 | <ol style="list-style-type: none"> 1. Supports multi-language on system name and location of Smart switches. 2. Add Microsoft Windows Authenticode. |
| v2.10.02 | <ol style="list-style-type: none"> 1. If the switch is failed in firmware upgrade, the switch will be in loader mode and marked as red color in device list for easily differentiation. If the switch is in loader mode, it cannot be configured and only allowed firmware upgrade through SmartConsole Utility. 2. The latest SmartConsole Utility is able to select multiple switches to upgrade firmware at a time. It can offload the maintenance of administrator. |
| v2.01.09 | N/A |
| v2.01.06 | Implement new user interface. |
| v1.07 | N/A |
| v1.06 | N/A |
| v1.05 | N/A |
| v1.04 | <ol style="list-style-type: none"> 1. Change the utility name from web_management_utility to SmartConsole Utility. 2. Add multicast mechanism. <ol style="list-style-type: none"> A. Add DHCP refresh function, function bit map. B. It is backward compatible with web_management_utility. |
| v1.03 | N/A |

Problem Fixed:

| Version | Detail |
|----------|---|
| v2.10.05 | <ol style="list-style-type: none"> 1. Fix the bug that only one NIC can send IGMP report even multiple NICs were installed on the PC running SmartConsole Utility. 2. Fix the bug that Device Setting allows device IP same as Gateway IP. 3. Fix the bug that monitor function can only be done when the device is in the same subnet as the PC which installed SmartConsole Utility. |
| v2.10.02 | N/A |
| v2.01.09 | <ol style="list-style-type: none"> 1. Fix the bug that utility could not be installed completely on some of operating systems (Windows XP/2k in English version). 2. Fix the bug that the device will not be allowed to upgrade firmware through SmartConsole utility when the device upgraded firmware failure in Web |

| | |
|----------|--|
| | <p>GUI.</p> <p>3. Display LLDP & SNMP in the device list.</p> |
| v2.01.06 | N/A |
| v1.07 | Wording changes. |
| v1.06 | <ol style="list-style-type: none"> 1. Fix the bug that if users upgrade wrong firmware in load mode it will not pop up triple error message continuously. 2. Fix error message bug. These three conditions may cause the unexpected "Password error" to occur: <ol style="list-style-type: none"> a. The Logitech ® SetPoint program is installed on the host PC. b. The IBM ® TrackPoint program is installed on the host PC. c. The infection of the "Trojan-PSW.Win32" program. |
| v1.05 | Change "Group Timer" keyword to "Group Interval". |
| v1.04 | N/A |
| v1.03 | Fix the bug that the device information shown does not match the selected one when upgrading process in monitor list. |

Related Documentation:

- Smart III: DES-1210 Series User Manual
- Smart III: DGS-1210 Series User Manual
- Smart II: DES-1200 Series User Manual
- Smart II: DGS-1200 Series User Manual